

## Storage Guide




**Careful Storage ensures maximum benefits** - Hermes abrasives are high quality tools and as such require corresponding storage considerations. Improper storage and handling may have adverse effects on performance. Particular care must be taken in the storage of glue bonded products as they are more susceptible to surrounding climatic conditions than resin bonded or waterproof products.

### OPTIMAL STORAGE CONDITIONS

- Room Temperature 18 - 22°C
- Relative Humidity 45 - 65%
- If possible, store in original packaging on shelves, pallets or stands.
- Products should be used in the order they are received

### UNSUITABLE STORAGE CONDITIONS

- Near sources of heat such as heaters or radiators
- Extreme temperature fluctuations
- Storage directly on concrete or stone floors
- Unheated rooms in winter



With belts, once carton has been opened, hang all belts accordingly. Hang the belts for at least 24 hours prior to use.

Please Note:

The above recommendations are a guide only. Individual requirements may vary. Please contact your Sales Representative for tailored advice to suit your requirements.